



2/2/04

5050 First Avenue S., Suite 102 61/29/04
Seattle, WA 98134
P.O. Box 1730
Seattle, WA 98111
(206) 764-3000
Fax: (206) 764-3012

RECEIVED

JAN 30 2004

5900 W Marginal Way SW 98106 PUGET SOUND CLEAN
AIR AGENCY


FAX TRANSMISSION COVER SHEET

Date:	1/29/04
To:	Elizabeth Gilpin
Fax:	343-7522
Subject:	Seattle Cement Terminal
Sender:	Tom Hanson

**YOU SHOULD RECEIVE 2 PAGE(S), INCLUDING THIS COVER SHEET. IF YOU DO
NOT RECEIVE ALL THE PAGES, PLEASE CALL (206) 764-3042**

Per our telephone conversation this
morning.

Tom H.



Glacier Northwest, Inc
INTERNAL RELEASE INVESTIGATION REPORT**Section 1—Release Information**

Use the reverse of this form to provide additional details.

Site of release: SEATTLE CEMENT TERMINALDate: 1/29/04 Time: 0830 Time release contained: 0840Material released: CEMENT Estimated quantity of release: 3-5 minCause of release: DURING FILLING OF LOADOUT #4, SOME MATERIAL WAS SHUNNED TO A PARTIALLY FULL LOADOUT SILO; FAULTY VALVING IS SUSPECTEDNature and extent of any injuries: N/ASpecific release location (describe the area and identify the source of the release): FROM PORT ON TOP OF SILO; PORT CAP BLOWN OFF BY PRESSURE IN LOADOUT #3 SILO

Description of surrounding areas (identify any environmentally sensitive features of the surroundings):

Duwamish River is 100 yards awayAffected surface (check all that apply): ☐ Pavement ☐ Bare Ground ☐ Water N/ADid the material reach any drains, storm sewers, or surface water? ☐ Yes ☒ NoWeather conditions (check all that apply): ☐ Clear ☐ Overcast ☒ Raining ☐ Snowing**Section 2—Response Information**Actions taken to stop release: SHUT DOWN OPERATIONSActions taken to clean up release: COLLECTED MATERIAL AND RETURNED LOADOUT #3 SILOActions taken to prevent a recurrence: INVESTIGATION OF VALVE FAILURE & REVIEWING PROCEDURES WITH PLANT OPERATORSReporting sequence: TERMINAL OPERATOR → ASST. MGR → ENVIRONMENTAL MGR → PSCAA

Report Completed by:

Name: STEVE PENSWICK Date: 1/29/04Signature: Steve Penswick

Copies of the completed report must be forwarded to the
Washington Division Environmental Manager